National Transportation Safety Board NTSB ID: DEN03LA024 Aircraft Registration Number: N252DR FACTUAL REPORT Occurrence Date: 12/10/2002 Most Critical Injury: None Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone CO 81637 1115 **MST** Eagle Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft Mooney M20K Airplane Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On December 10, 2002, about 1115 mountain standard time, a Mooney M20K, N252DR, registered to and operated by Flying M-U-2, Inc., was substantially damaged during a forced landing following a loss of engine power at the Eagle County Airport, Eagle, Colorado. The private and student pilot were not injured. Day visual meteorological conditions prevailed, and a VFR flight plan had been filed for the personal flight being conducted under Title 14 CFR Part 91. The flight had just originated and was en route to Waco, Texas.

According to the pilot's accident report, about 10 seconds after the airplane lifted off the runway, he realized "the cowl plugs had been left in the cowl holes. Fearing engine/propeller entanglement with [the] cord connecting the two front plugs, [he] attempted to reland on [the] same runway." The airplane touched down but there was insufficient runway remaining to come to a safe stop. The pilot elected to abort the landing, resulting in the airplane "not regaining the air." The airplane went off the end of the runway and traveled about 300 feet across rough terrain before the nose landing gear collapsed.

After NTSB was notified of the accident, the pilot was contacted via telephone and asked what had happened. He said that after the airplane lifted off the runway and had climbed 50 feet, the engine lost power. He attempted to land on the 2,000 feet of runway remaining. The airplane touched down, traveled approximately 300 feet before going off the end onto soft, muddy ground. Airport emergency personnel who responded reported to NTSB that they found the protective coverings for the engine air scoops still in place. Postaccident examination further revealed wrinkling of the fuselage behind the firewall, and a 4-inch hole in the fuselage. The horizontal stabilizer was also damaged.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN03LA024

Occurrence Date: 12/10/2002

AVIATION			Occurrence Type: Accident										
Landing Facility/Approach In	formation												
Airport Name	Airport	ID:	Airport Elevat	t Elevation Runway Used			Runway Length		th	Run	way Width		
Eagle County Regional EG					6535 Ft.	MSL	25	25 8000			00		
Runway Surface Type: Asphalt													
Runway Surface Condition: Dry													
Type Instrument Approach: Unknown	own												
VFR Approach/Landing: Unknown	า												
Aircraft Information													
Aircraft Manufacturer			- 1	lodel/S	eries						al Number		
Mooney			N.	И20K						25-10	038		
Airworthiness Certificate(s): Norm	al												
Landing Gear Type: Retractable	- Tricycle												
Homebuilt Aircraft? No					Max Gross W	3200 LBS Number			er of Er	ngines	:: 1		
= - 11				Engine Manufacturer: Model/Series: TSI0-520-NB									ed Power: 5 HP
- Aircraft Inspection Information													
Type of Last Inspection Da				Date of Last Inspection Time Si			Since Last Inspection			Airfrar	ne To	tal Time	
Annual			08/20	08/2002					54 Hours			3534 Hours	
- Emergency Locator Transmitter (ELT) Information												
ELT Installed? Yes	ELT Operat	ed? Ye	es			ELT	⊺ Aided i	n Locating A	ccident S	Site? No)		
Owner/Operator Information													
Registered Aircraft Owner	Str	Street Address 615 Baker La.											
Flying M-U-2, Inc.			City	City								ie	Zip Code
			Str	Waco TX 76									76708
Operator of Aircraft		Same as Reg'd Aircraft Owner											
Same as Reg'd Aircraft Owner				City							Stat	te	Zip Code
Operator Does Business As: Operator Designator Code:													
- Type of U.S. Certificate(s) Held:	None												
Air Carrier Operating Certificate(s)	:												
Operating Certificate:					Operator C	ertific	cate:						
Regulation Flight Conducted Unde	r: Part 91: Genera	al Aviat	tion		1 .								
Type of Flight Operation Conducted													
		FACT	UAL R	EPOR	T - AVIATI	ON							Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN03LA024

Occurrence Date: 12/10/2002

AVIATI	Occurrence Type: Accident											
First Pilot Information												
Name					City				St	ate	Date of Birth	Age
On File					On File				Or	n File	On File	58
Sex: M Seat Occupied	wn	Certificate Number: On File										
Certificate(s): Private												
Airplane Rating(s): Single-engine Land												
Rotorcraft/Glider/LTA:												
Instrument Rating(s): Airplane												
Instructor Rating(s): None												
Type Rating/Endorsement for	or Accident/In	cident Aircra	ft? No			С	urrent Bier	nial Fligh	t Revie	w? 03/	2002	
Medical Cert.: Class 3	Medica	al Cert. Status	s: Valid Med	dicalw/ wa	ivers/lim	١.		Date of	Last M	1edical E	Exam: 03/2001	
- Flight Time Matrix	me Matrix All A/C This Make and Model Airplane Single Engir		Airplane Single Engine	Airplane Mult-Engine	Night		Inst Actual	Instrument al Simulated		Rotorcraft	Glider	Lighter Than Air
Total Time	1419	900	1419			45 157		7	64		4	
Pilot In Command(PIC)	1419	900	1419			45	157	<u>'</u>	64			
Instructor	0.5	0.5	0.5			_						
Last 90 Days Last 30 Days	35 16	35 16	35 16			1	2		_			
Last 24 Hours	10	10	10					-	\neg			
Seatbelt Used? Yes	Shou	lder Harness	Used? Yes		Т	oxico	ology Perfo	med? No		s	Second Pilot? No)
Flight Plan/Itinerary												
Type of Flight Plan Filed: VF	-R											
Departure Point					S	State Airpoi		Airport Identifier		Departure Time		Time Zone
Same as Accident/Incide	nt Location					EGE		EGE		1115		MST
Destination	S	State Airp		Airport Identifier								
Waco	Т	TX ACT										
Type of Clearance: Unknown												
Type of Airspace: Class	D											
Weather Information												
Source of Briefing: Flight Service Station												
Method of Briefing: Telephone												
FACTUAL REPORT - AVIATION Page 3												

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN03LA024

Occurrence Date: 12/10/2002

Occurrence Type: Accident

	Occurrenc	Occurrence Type: Accident												
Weather Information														
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF Di	istance Fro	m Accid	dent Site		Direction From Accident Site				
EGE	1115	MST	6535 Ft.	. MSL				NM		Deg. Mag.				
Sky/Lowes	st Cloud Condition: Clear	r		Ft. AGL					Condition of Light: Day					
Lowest Ce	eiling: None	Ft.	Ft. AGL Visibility:			10	SM	Altiı	meter:	30.18	"Hg			
Temperatu	ıre: -8 °C [Dew Point:	-12 °C	°C Wind Direction: Density							5103	Ft.		
Wind Spee	ed: Calm	Gusts:		Weather Condtions at Accident Site: Visual Conditions										
Visibility (R	RVR): Ft.	Visibility (R)	VV)	SM	Intensity	y of Precipit	tation:							
Restriction	ns to Visibility: None		,											
Type of Pre	ecipitation: None													
Accident	Information													
Aircraft Dar	mage: Substantial		Aircraft Fire	e: None	Aircraft Explos					osion None				
Classificati	ion: U.S. Registered/U.	.S. Soil												
- Injury Sur	mmary Matrix	Fatal Se	erious Mino)r	None	TOTAL								
First Pi	ilot				1	1	ī l							
Second	d Pilot						7							
Studen	nt Pilot						1							
Flight I	nstructor						1							
Check	Pilot						1							
Flight E	Engineer						7							
Cabin /	Attendants						7							
Other C	Crew						7							
Passen	ngers				1	1	<u>-</u>							
- TOTAL /	ABOARD -				2	2	2							
Other G	3round						1							
- GRAND	O TOTAL -				2	2	2							

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: DEN03LA024

Occurrence Date: 12/10/2002

Occurrence Type: Accident

	rativ			

Investigator-In-Charge (IIC)

Arnold W. Scott

Additional Persons Participating in This Accident/Incident Investigation:

Harold A Wayman Aviation Safety Inspector - Operations FAA Flight Standards District Office 26805 East 68th Avenue, Suite 200 Denver, CO 80249